	Property is: Single Fam	nily X Duple:	C Other	
Date:	9/27/2010		_	
selow is the <u>r</u>	ninimum requirement to meet he	— ealth and safety issue	s. The City of Milwaukee, the Redevelopment	Authority, and their representatives
			te, or for omissions through error or oversight. deral Block Grant or HOME programs.	The list does not necessarily include
·		inputities, of by the re	actal Block Grant of Flowing programs.	
	Condition Report			
ocation	Required Work Landscaping	n/a 🗶 Yes	Note/Comments Self Help	Cost \$
, itc	Steps/Handrails	n/a X Yes		\$ \$
	Service walks	n/a X Yes]	\$
]	·
	Fencing		<u></u>	\$
	Parking	n/a X Yes	<u></u>	\$
	Retaining walls	n/a X Yes L		\$
	Other	n/a Yes		\$
arage	Other	n/a Yes		\$
ou. ugo	Singles: repair	n/a X Yes]	\$
	Shingles: Roof over existing	n/a X Yes]	\$
	Shingles:Tear off & re-roof	n/a X Yes]	\$
	Gutters/downspouts	n/a Yes X	Install	\$ 200.00
	Flashing	n/a X Yes]	\$
	Eaves	n/a X Yes]	\$
	Siding	n/a X Yes]	\$
	Doors	n/a Yes X	Replace Service Door	\$ 200.00
	Windows	n/a X Yes]	\$
	Slab	n/a X Yes]	\$
	Paint	n/a Yes X	Trim / Main Door	\$ 150.00
	Electrical	n/a X Yes]	\$
	Other	n/a Yes	1	\$
orches	Ollion		_	Ψ
	Roof	n/a X Yes		\$
	Deck-upper	n/a X Yes]	\$
	Decklower	n/a X Yes		\$
	Steps/handrails	n/a X Yes]	\$
	Ceiling	n/a Yes X	Repairs	\$ 100.00
	Guardrails	n/a X Yes]	\$
	Structural	n/a X Yes]	\$
	Doint	n/o	 1	¢ 150.00

n/a

Other

Yes 🗌

\$

House

Chimney	n/a Y	∕es X	Repairs	\$ 250.00
Shingles: repair	n/a X	es 🗌		\$
Shingles: Roof over existing	n/a X Y	es 🗌		\$
Shingles:Tear off & re-roof	n/a 🔲 Y	es X	North Side	\$ 2,500.00
Gutters/downspouts	n/a X Y	es 🗌		\$
Flashing	n/a X Y	es 🗌		\$
Eaves	n/a X Y	es 🗌		\$
Siding	n/a X Y	es 🗌		\$
Storm Doors	n/a 🔲 Y	es X	Front Storm	\$ 200.00
Prime ("main") Doors	n/a X Y	es 🗌		\$
Storm Windows	n/a 🔲 Y	es X	6 Storms	\$ 600.00
Prime ("main") Windows	n/a X Y	es 🗌		\$
Paint	n/a 📗 Y	es X	Trim	\$ 900.00
Foundation	n/a X Y	es 🗌		\$
Electrical	n/a X Y	es 🗌		\$
Other	n/a Y	es 🗌		\$
Other	n/a Y	es 🗌		\$
Other	n/a Y	res 🗌		\$
Other	n/a 🔲 Y	es		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

5,250.00

Interior Co	ondition Report				
	Unit: Entire unit (single family) Upper unit of duplex	X		Lower unit of duplex Other	
Mechanical	Required Work				
Heating	Repair/replace boiler	n/a X	Yes		\$
	Repair radiation	n/a X	Yes		\$
			Yes		\$
	Repair/replace furnace		Yes		
	Repair ductwork	n/a X			\$
	Replace thermostat	n/a X	Yes _		\$
	Repair/replace grilles	n/a X	Yes _		\$
Electrical	Tune boiler/furn. insp ht exchang	g∈n/a X	Yes		\$
	Repair/replace receptacles	n/a X	Yes		\$
	Repair/replace switches	n/a X	Yes		\$
	Repair/replace fixtures	n/a	Yes X	4 Fixtures	\$ 200.00
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Upgrade service	n/a X	Yes		\$
	Other	n/a	Yes		\$
	Other	n/a	Yes		\$
Plumbing	Repair/replace kitchen sink	n/a	Yes X	Replace	\$ 200.00
		n/a			50.00
	Repair/replace kitchen sink fauce		Yes X	Replace	\$
	Repair/replace tub	n/a	Yes X	Replace	\$ 500.00
	Repair/replace tub faucet	n/a	Yes X	Replace	\$ 40.00
	Repair/replace toilet	n/a	Yes X	Replace	\$ 200.00
	Repair/replace lavatory	n/a	Yes X	Replace	\$ 100.00
	Repair/replace lavatory faucet	n/a	Yes X	Replace	\$ 30.00
	Repair/replace wash tub	n/a X	Yes		\$
	Repair/replace wash tub faucet	n/a X	Yes		\$
	Unclog piping:	n/a X	Yes		\$
	Repair drain/waste/vent piping	n/a	Yes X		\$ 150.00
	Repair water piping	n/a	Yes X		\$ 200.00
	Repair/replace water heater	n/a X	Yes		\$
	Other	n/a	Yes X	Kitchen Cupboard	\$ 400.00

\$

n/a Yes

Other

Windows					
	Replace broken glass	n/a χ Yes]	\$	
	Repair or replace sash	n/a X Yes		\$	
Doors	Repair or replace doors	n/a 💢 Yes	1	\$	
	Repair or repl. locks/latches	n/a X Yes	Self Help	\$	
Walls/Ceilin	gs				
	Repair or repl. @ defective	n/a Yes X	Repairs	\$	3,000.00
Paint	Repair or repl. @ defective	n/a Yes 🔀	Complete Unit	\$	1,000.00
	Tropan of Topi. © dolocaro	174 100 X	Complete Cinc	Ψ	1,000100
Fire Safety	Install smoke alarm:bsmt.	n/a X Yes	Self Help	\$	
	Install smoke alarm: 1st flr.	n/a X Yes	Self Help	\$	
	Install smoke alarm: 2nd flr.	n/a X Yes	Self Help	\$	
Handrails	Repair/replace defective	n/a X Yes	Self Help	\$	
Stairs	Repair defective	n/a 💢 Yes]	\$	
Floors	Repair defective	n/a Yes X	Complete 1st Floor	\$	2,500.00
Other	Repair defective	11/a 163 X	Complete 1st 1 looi	Ψ	2,300.00
		n/a Yes		\$	
		n/a Yes		\$	
		n/a Yes]	\$	
		n/a Yes]	\$	
			Interior: Estimated Cost:	\$	8,570.00
			Total Exterior and Interior Cost:*	\$	13,820.00

Prepared by: S. Denny / Inspected by: Paul Geboy Date: 9/28/10

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.